



Health Facility Guidelines

Sample – Assessment Report

No	Room number	Room Name	Design Code	Comment	Consultant Response
LEVEL B02					
Medical Staff Changing Rooms					
001			General	There appear to be no provisions for house keeping on this floor, other than the HK (is this house keeping?) rooms 55.1110 and 53.086. This appears to be unsatisfactory and a more even distribution over the large floor plate would be preferred.	
002		Anteroom WC / Shower	General	The number of basins (in relation to the number of toilet pans) is very low. Even if compliant with local codes, our advice is to increase the number. This is most apparent in 52.142 and 52.211.	
003		Locker Rooms	General	The changing rooms ideally should allow space for seating, dirty linen skips and waste bins. Some rooms also may need clean attire storage.	
004		WC / Shower HC	ADA4.1.3 (21)	5% of the changing rooms are to be accessible	
005	52.231, 52.510	Lockers Rehabilitation	General	The entrance to these rooms is right on the opposite side of the lift bank and unnecessarily increases the travel distance. It would make more sense to mirror these rooms with the expansion area.	
006	52.034, 52.128	House Keeping		We have assumed this room to be house keeping. If this is the case, as a minimum the room should have a floor receptacle or service sink and storage space for house keeping supplies. A wash hand basin may be required for infection control purposes.	
007	52.134	Anteroom WC / Shower	General	Wash hand basins are missing.	
008	55.121	WC / Shower HC Female	ADA4.13.6	The entry door is not accessible.	
009	51.145	Locker HC Female	ADA4.13.6	Ensure the entry door has no latch combined with a closer – otherwise this door is not accessible.	
0010	48.811	Circulation Area	ADA4.13.6	If this is an accessible route, ensure the entry door has no latch combined with a closer – otherwise this door is not accessible.	

The Indian Health Facility Guidelines recommends the use of **HFBS** “**Health Facility Briefing System**” to edit all room data sheet information for your project.

HFBS provides edit access to all HFG India standard rooms, departments, and more than 40 report templates.

HFBS Health Facility Briefing System



Briefing Module

The Health Facility Briefing System (HFBS) has numerous modules available via annual subscription. It suits healthcare Architects, Medical Planners, Equipment Planners Project Managers and Health Authorities.

Use the HFBS Briefing Module to quickly drag in health facility departments or pre-configured room templates from the HFG standard, edit the room features such as finishes, furniture, fittings, fixtures, medical equipment, engineering services. The system can print or download as PDF more than 100 custom reports including room data sheets, schedules, and more...

To learn more about the HFBS web-based Healthcare Briefing and Design Software and to obtain editable versions of the “Standard Components” including Room Data Sheets (RDS) and Room Layout Sheets (RLS) offered on the HFG website, signup for HFBS using the link below.

Get Started Now:
hfbs.healthdesign.com.au

- ✓ HFG India Room Data Sheets and Departments are instantly editable in the HFBS software available online in the HFBS India Domain.
- ✓ You can access hundreds of report templates to print your HFG India room data in HFBS.
- ✓ HFBS has a onetime free 3 day trial available to all new users – signup for the HFBS India Domain today.

Get Started Now:
hfbs.healthdesign.com.au



HFBS

Health Facility Briefing System

hfbsinfo.com | techsupport@healthdesign.com.au